Product Brief

ZigBee® Certified product

ZBHT-2—Model #1015C

Wireless Temperature and Humidity Sensor with LCD

The ZBHT-2 wirelessly communicates temperature and humidity readings using the ZigBee Pro protocol and the Home Automation (HA) profile.

When used in conjunction with the Harmony Gateway or Harmony Platinum, the ZBHT-2 will display readings for temperature and humidity on a mobile device or desktop computer. When a router device or the coordinator is open for joining, the ZBHT-2 easily joins the ZigBee mesh network upon installation of the batteries. It will then automatically send signals to the designated receiving device with continual updates or according to the configuration set by the user.



Benefits

- Remotely monitor the temperature and humidity in one location or in multiple locations by placing several ZBHT-2 devices anywhere measurement is desired.
- Locally view temperature, humidity and battery level by button press.
- Data is detected and automatically sent to the control center application.
- Small size and convenient connectivity means easy retrofit ability and virtually no installation cost.
- Place anywhere indoors or purchase specially designed outdoor mount which sheds dust and repels rain.
- Low power consumption means long battery life.
- Low battery alert is sent to the display.
- Sends messages via ZigBee, a wireless RF protocol that is rapidly becoming the standard for energy management. Enables appliances to become part of the smart ecosystems of tomorrow.

SPECIFICATIONS:			
Technical			
Power Supply:	2 AA Batteries		
Communication Range:	50 meters 30 meters in outdoor housing		
Operating Ambient:	Temperature: -10~50°C Humidity max. 10~90%		
Accuracy:	Temperature: +/- 0.5°C Humidity: +/- 4.5%		
Mechanical			
Size:	4.25" L X 1.35" W X .75" H		
Weight:	1.1 Oz.		
Mounting:	Indoor - place anywhere with- in temperature limits. Out- door - mount to wall or pole using specially designed hous- ing.		
Operation			
Local Control:	Yes, and automatic		
ZigBee [®] function:	ZigBee Pro End device		



OTHER SPECIFICATIONS:		
Indicators:	LCD flashes and displays words and icons to indicate network status, binding mode and fault conditions. LCD does not remain lit; it stays off to conserve battery life.	
Program Buttons:	Button 1 — toggles display to show temperature, humidity, and battery power level Button 2 — used for joining network, permit joining, binding, and device announce.	
ZigBee function:	Manufacturer ID: 0x1075; ZigBee Pro End device	

HA Profile: (0x0104)		Device ID: 0x0302 HVAC Temperature Sensor		
End Point: 0x0A				
Cluster Name	Client/Server	Cluster Description		
Basic	Server	Attributes for determining basic information and setting and enabling device		
Power Configuration	Server	Attributes and commands for configuring power		
Identify	Server	Attributes and commands for putting a device into Identification mode		
Alarm	Server	Attributes and commands for sending notifications and configuring alarm functionality		
Temperature Measurement	Server	Attributes and commands for temperature measurement		
Humidity Measurement	Server	Attributes and commands for humidity measurement		
	Cluster Name Basic Power Configuration Identify Alarm Temperature Measurement Humidity	Cluster Name Client/Server Basic Server Power Configuration Server Identify Server Alarm Server Temperature Measurement Server Humidity Server		

